

!!! IMPORTANT!!! Read First Before Installing Software

When installing V3.60 software on CEREC Acquisition Units, the Acquisition system configuration setting may be incorrectly set to Scanner instead of 3D camera. This will prevent your 3D camera from activating when taking optical impressions.

To correct this follow the steps listed below:

1. After the V3.60 software update has been installed, open the program.
2. Click on the Settings menu
3. Move your cursor to Configuration
4. Click on Acquisition system
5. Select 3D camera and click OK

